

PUNE MUNICIPAL CORPORATION

Parvati Water Works Laboratory

Report ID CH130 COLOR

Date:

पर्वती जलकेंद्र पुणे ३०.

25/04/2025

Amount (Rs.): 1620.0वक क्र.- ८H-130

Report of Water Samples Collected as on 22/04/2025

Challan Date: 22/04/2025

मालकाचे नाव: Indian Model International School

Challan No: 12423000002

1) Indian Model International School, OPP. Nyati equinox Near PVPIT College, Bavdhan Pune 411021 R.O Water

As per I.S Standard No. 10500:2012				
Parameter	Results	Desirable Limit	Permissible Limit	Unit
PH	7.4	Between 6.5 To 8.5	No Relaxation	_
Turbidity	0.3	Max 1	Max 5	N.T.U
Total Hardness (as CaCO ₃)	61.0	Max 200	Max 600	PPM
Chlorides (as CI)	22.0	Max 250	Max 1000	PPM
Alkanity (as calcium carbonate)	66.0	Max 200	Max 600	PPM
Nitrate Nitrogen (as NO ₃)	1.2	Max 45	No relaxation	PPM
Nitrite Nitrogen (as NO ₂)	0.08	-		PPM
Coliform	0	0	0	100ml
E-Coli	0	0	0	100ml
Residual Chlorine Test	Nil	0.2	-	PPM

Remark: सदरचा नमुना / नमुने मालकांनी स्वतः आणून दिला. उपरोक्त नमुना / नमुने हा प्रातिनिधिक असल्याचे गृहीत धरले आहे. सदरचा अहवाल हा वैयक्तिक माहितीसाठी असून ,याचा वापर कुठल्याही प्रकारचा परवान्यासाठी केल्याने उद्दभवणाऱ्या कायदेशीर बाबींस हे कार्यालय जबाबदार असणार नाही.तसेच नमुनांच्या उद्दगमाविषयीचा पडताळा ह्या कार्यालयामार्फत केलेला नाही.

शेरा:

The Above Water Sample is Potable as per IS10500:2012. Due to Purifier Water Sample, Residual Chlorine Test is Not Found.

> 25/04/2025 (Mandar Sardeshpande)

Chemist

Water Supply Department Pune Municipal Corporation

Manager

Indian Model International School, Bavdhan, Pune

INDIAN MODEL INTERNATIONAL SCHOOL

BAVDHAN, PUNE - 411021

सदर अहवाल संगणकीकृत असल्याने सहिची आवश्यकता नाही.

Page 1 of 1

6/04/2025

Annexure C (APPENDIX XIII)

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No.

Dated: 02/05/2025

It is certified that an inspection team headed by Mr.Ram Sonawane (Divisional Sanitary Inspector) from Pune Muncipal Corporation Parvati Water Works Laboratory Health Department inspected the Indian Model International School ,Bavdhan,Pune on (02/05/2025) and on the basis of Water Test Report Attached bearing no (CH 130) dated -25/04/2025 of Pune Municipal Corporation Parvati Water Works Laboratory certified that the Indian Model International School Bavdhan, Pune, has safe drinking water facilities for the students and members of staff of the institution.

School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed

by the Central/ State/ U.T. Govt.

This certificate is valid till May 2026

वरिष्ठ आरोग्य निरीक्षक कोथरुड-बावधन क्षेत्रिय कार्याल

Signature with Seal: मुणे महानगरमालिका

Name:

Mr.Ram Sonawane

Designation

Divisional Sanitary Inspector

Name & Address of the Office/Department: --Kothrud bhavdhan Divisional Office.

To Indian Model International School Sr,no.35/1/48/2/A/8(ps-20), (old sr no-35/1/1/B), Bavdhan kh, Ta.Mulshi Dist.Pune

66 | Page

INDIAN MODEL INTERNATIONAL SCHOOL BAVDHAN, PUNE - 411021

Indian Model International School, Bavdhan, Pune